



Bendix Magneto Impuse coupling replacement

Steps to remove the impulse coupling.

Written By: Kelsi English



INTRODUCTION

A failed impulse coupling can cause the crankshaft gear to break off. This will cause the aircraft's magneto not to work therefore the aircraft's engine will not start.



TOOLS:


- [9 16 wrench](#) (1)
 - [Large Needle Nose Pliers](#) (1)
-

Step 1 — Impulse Coupling





- Use a 9/16 wrench to unscrew the nut on the drive shaft.

Step 2



- Remove the lock washer underneath the nut.

Step 3



- Pull away the impulse coupling.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-21 02:00:58 PM.